



# Kenco Engineering, Inc.

Longer Wear Parts for Slat Floors

New Product

***Tired of breaking your slat chain to replace broken liner plates?***



***Kenco part # K-1519-34-SL***

***Kenco has the solution!***

- 3/4" thick "Alloy-K700" provides exceptional life
- Guaranteed for 5 million tons (see website at [www.kencoengineering.com](http://www.kencoengineering.com) for more details)
- Two piece design allows replacement without breaking the slat chain
- Bolt-hole template is available for easy retrofit in place
- Save your back! Split liners weigh half as much for an easier and safer installation
- The new K-1519-34-SL replaces Kenco K-1536-34-700




*Still proudly made in the USA*



**Kenco Engineering, Inc.**  
P.O. Box 1467  
Roseville, CA 95678  
800-363-9859  
[www.kencoengineering.com](http://www.kencoengineering.com)

Distributed by:



K-1519-34-SL Split Slat Floor Liner